DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/18/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 02			(X3) DATE SURVEY COMPLETED	
		155678	B. WING	B. WING		R 09/15/2015	
NAME OF P	ROVIDER OR SUPPLIER				STREET ADDRESS, CITY, STATE, ZIP CODE	1 09/	13/2013
					800 ST JOSEPH DR		
WATERFO	ORD PLACE HEALTH CA	MPUS		KOKOMO, IN 46901			
(X4) ID	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID		PROVIDER'S PLAN OF CORRECTION		(X5)
PREFIX TAG			PREFI TAG		(EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		COMPLETION DATE
{K 000}	INITIAL COMMENTS		{K 0	000	}		
	A Post Survey Revisi	it (PSR) to the Life Safety					
	-	and State Licensure Survey					
		6 was conducted by the					
	Indiana State Departr	•					
	accordance with 42 C	CFR 483.70(a).					
	Survey Date: 09/15/1	15					
	Facility Number: 002	667					
	Provider Number: 15	5678					
	AIM Number: 200300	0090					
	Surveyor: Phillip Kon Specialist	nsiski, Life Safety Code					
	At this PSR survey M	Vaterford Place Health					
	Campus was found in						
	Requirements for Par	•					
		2 CFR Subpart 483.70(a),					
		the 2000 edition of the					
	National Fire Protection	on Association (NFPA) 101,					
	Life Safety Code (LS0	C) and 410 IAC 16.2. The					
	original building (1) co	onsisting of 100, 200, 300,					
	400 and 600 halls wa	s surveyed with Chapter 19,					
	Existing Health Care	Occupancies.					
	This one story facility	was determined to be of					
	Type V (111) construc						
	sprinklered. The facil	ity has a fire alarm system					
		in the corridors, hard wired					
		dent sleeping rooms and					
		orridors. The kitchen was					
		ed living side separated from					
	-	with a two hour fire wall.					
		acity of 103 and had a					
	census of 84 at the tir	me of this survey.					
I A DODATODY	DIDECTOR'S OF PROVIDER/S	SUPPLIER REPRESENTATIVE'S SIGNATURE			TITI F	-	(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/18/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDIN	PLE CONSTRUCTION IG 01, 02		(X3) DATE SURVEY COMPLETED	
		155678	B. WING _			l	R 15/2015
	ROVIDER OR SUPPLIER PRD PLACE HEALTH CA	MPUS		800 ST	T ADDRESS, CITY, STATE, ZIP CODE JOSEPH DR DMO, IN 46901	1 03/	13/2013
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI) TAG				(X5) COMPLETION DATE
{K 000}	access were sprinkle	esidents have customary red and all areas providing sprinklered. The facility had	{K 0	00}			
{K 000}	Code Recertification a	t (PSR) to the Life Safety and State Licensure Survey 5 was conducted by the nent of Health in	{K 0	00}			
	Survey Date: 09/15/1 Facility Number: 002 Provider Number: 15 AIM Number: 200300 Surveyor: Phillip Kon Specialist	667 5678					
	Place Health Campus with Requirements fo Medicare/Medicaid, 4 Life Safety from Fire, National Fire Protectic Life Safety Code (LSC Rooms 201 to 208 on (2) which is complete building was surveyed Health Care Occupant	2 CFR Subpart 483.70(a), the 2000 edition of the on Association (NFPA) 101, C) and 410 IAC 16.2. 200 hall of the new building by separate from the original d with Chapter 18, New ocies.					

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/18/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01, 02		(X3) DATE SURVEY COMPLETED	
		155678	B. WING			R 09/15/2015	
NAME OF PROVIDER OR SUPPLIER WATERFORD PLACE HEALTH CAMPUS			STREET ADDRESS, CITY, STATE, ZIP CODE 800 ST JOSEPH DR KOKOMO, IN 46901		CODE	09/13/2013	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG	X (EACH CORRECTIVE ACT CROSS-REFERENCED TO T	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		
{K 000}	with smoke detection smoke detectors residual spaces open to the collocated on the assiste the rest of the facility. The facility has a cap census of 84 at the till All areas where the reaccess were sprinkled.	in the corridors, hard wired dent sleeping rooms and bridors. The kitchen was ed living side separated from with a two hour fire wall. acity of 103 and had a me of this survey. esidents have customary red and all areas providing sprinklered. The facility had	{K 0	000}			